




# CHATHAM FIRE STATION

---

EXISTING CONDITIONS VISUAL SURVEY

# MEDICAL TREATMENT AREA



Chatham Fire Department Existing Conditions Visual Survey

# RECORDS STORAGE



Chatham Fire Department Existing Conditions Visual Survey

# LOCKER ROOMS



Chatham Fire Department Existing Conditions Visual Survey



# TRAINING AREA/BUNK ROOM #1



Chatham Fire Department Existing Conditions Visual Survey

# BUNK ROOMS - SECOND FLOOR



# RESTROOMS - FIRST FLOOR

MEN'S ROOM



WOMEN'S ROOM



Chatham Fire Department Existing Conditions Visual Survey

# RESTROOM - SECOND FLOOR



Chatham Fire Department Existing Conditions Visual Survey



# STORAGE AREAS




Chatham Fire Department Existing Conditions Visual Survey

Unsafe electrical  
panels




Ceiling  
patched  
with duct-  
tape



Chatham Fire Department Existing Conditions Visual Survey

# EQUIPMENT BAY

Water damage on ceiling




# TELECOMMUNICATION SETUP



Telephone and server installation located in Basement of Police Station



# TELECOMMUNICATION SETUP Cont.



Telephone/computer and radio wiring located in attic crawl space

# COMMUNICATION EQUIPMENT



Chatham Fire Department Existing Conditions Visual Survey



# EQUIPMENT BAY



Inadequate  
access to  
vehicles and  
equipment



# EQUIPMENT BAY



Chatham Fire Department Existing Conditions Visual Survey



# EQUIPMENT BAY/STORAGE AREA



Chatham Fire Department Existing Conditions Visual Survey

# EXTERIOR CONDITIONS



Chatham Fire Department Existing Conditions Visual Survey

# EXTERIOR CONDITIONS



Chatham Fire Department Existing Conditions Visual Survey